



Contract No. 009359	Station Section 2	Mile/Line: I-82	C/S <div></div>
Staked by SURVEY 5/6/2019	Date	Work Started Date 6/6/2019	Work Completed Date <div></div>
Calculated by Scott Busby 10/5/2019	Date	Checked by E. Knudson 10/1/2019	Inspector Scott Busby 10/5/19

ITEM NO. 17
Section 2 - I-82 Umatilla to Ellensburg
BEAM GUARDRAIL ANCHOR TYPE 10

Group Number 20

6/13/2019 - I-82

- Station MP 102.83 LT WB - Sheet 4 - Installed **One EA** Beam Guardrail Anchor Type 10
- **12.5 LF**
- **2** wood posts

Sub Total: - **1 EA** Beam Guardrail Type 10Anchor
 - **12.5 LF**Beam Guardrail Type 31
 - **2 EA** Beam Guardrail Type 10Anchor

Notes:

How Measured: Per Each - Checked in the field as installed

Item Num	Material Brand Name/Model Type	Manufacturer	Brand Name/Model Type	RAMS/QPL Ref. No.	Appr/Acc Code	Basis of Accept
017.03	Beam Guardrail Wood Post and Blocks	Superior Wood Treating		QPL-0005	2550	/ Lumber Grading Stamp or Grading Certificate and Certificate of Treatment. (If Aquatic Envir. Std. Spec. 9-09.3 (1) Applies)
017.08	Beam Guardrail Anchors	Trinity Highway Products, LLC		QPL-0003	2215	/ Manufacturer's Certificate of Compliance and Supporting Test Results

Item Num	Item Description	Grp	Date Work Complete	Unit	Quantity	Ledger Entry No.	Posted By Init.	Posted By Date	Checked By Init.	Checked By Date	Est. No.
0017	BEAM GUARDRAIL ANCHOR TYPE 10	20	10/5/2019	EAC H	1	313	EK	10/09/19			7

Attachments



Things to do 82-2.xlsx
Microsoft Excel
Worksheet
409 KB

DOT Form IP 422-635ER EF
Revised 4/2009